

INTERNATIONAL ASSOCIATION OF DRILLING CONTRACTORS

P.O. Box 4287 • Houston, Texas 77210-4287 USA 15810 Park Ten Place, Suite 242 • Houston, Texas 77084-5139 USA

Phone: 1/281 578-7171 • Fax: 1/281 578-0589

Chairman Bernie W. Stewart R&B Falcon Corp.

Vice Chairman
John R. Irwin
Atwood Oceanics Inc.

President Dr. Lee Hunt IADC

Secretary-Treasurer Thomas P. Richards Grey Wolf Drilling Company

International Service Center The Netherlands: P.O. Box 249 6710 BE Ede The Netherlands

Galvanistraat 88 6716 AE Ede The Netherlands

Phone: 31/318 645999 Fax: 31/318 645723

Washington Senior Vice President Government Affairs Brian T. Petty

1901 L Street, NW Suite 702 Washington, DC 20036-3506 USA

Phone: 1/202 293-0670 Fax: 1/202 872-0047

United Kingdom Wood International Center Craigshaw Drive, West Tulios Aberdeen AB12 3AG Scotland, U.K.

Phone: 44/1224-874800 Fax: 44/1224-875600

Middle East & Asia: P.O. Box 303 Mina Al-Fahal. Postcode 116 Muscat Sultanate of Oman Phone/Fax: 968-601180 19 March 1999

Minerals Management Service Attn: Rules Processing Team, MS 4024 381 Elden Street Herndon, VA 20170-4817 IN TRIPLICATE

Re: Update of Documents Incorporated by Reference

(RIN 1010-AC55)

Dear Rules Processing Team:

The International Association of Drilling Contractors supports, in principle, the proposal in today's *Federal Register* (64 FR 13535) to update the documents incorporated by reference by referencing the new edition of API RP 500 and adding API RP 505 as an alternative.

We remain concerned, however, about both the present structure of 30 CFR Part 250 and the proposed rewrite of Part 250 (63 FR 7335). As noted in our comments on the rewrite of Part 250, that proposed rule implies that API RP 500 is, by its incorporation by reference, the regulatory standard that must be met by mobile offshore drilling units (MODUs). However, both the current (16 December 1998) Memorandum of Understanding between MMS and the U.S. Coast Guard and its predecessor assigned responsibility for electrical hazardous area classification for MODUs to the Coast Guard. Unfortunately, MMS rules have not reflected this inter-agency agreement. This has resulted in both confusion and inappropriate attempts to enforce the API RP 500, rather than the Coast Guard's Electrical Engineering Regulations, on MODUs.

We hope that this source of confusion can be eliminated when the revised Part 250 is ultimately issued.

Sincerely,

Alan Spackman

Director, Offshore Technical and Regulatory Affairs